

0006

015/032 #2

GENWAL
RESOURCES, INC.

P.O. Box 1420 • 195 North 100 West • Huntington, Utah 84528
Telephone (801) 687-9813 • Fax (801) 687-9784

March 6, 1997

State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
1594 West North Temple
Box 145801
Salt Lake City, UT 84114-5801


Re: Highwall Survey; Crandall Cyn Mine, ACT/015/032.

Dear Sirs:


Attached is the completed highwall survey form sent us. From my understanding of one of the purposes of this survey Genwal will submit a permit amendment identifying this highwall and its reclamation.

Please call me if you have any questions

Sincerely



Gary E. Gray
Reclamation Engineer



UDOGM HIGHWALL SURVEY

February 1997

MINE NAME Crandall Cyn Mine

PERMIT NUMBER AG/015/032

1. Identify each highwall used in connection with the mine and provide a description of its location and extent. (reference maps where highwall is shown)

1 Highwall exists with the mine portals. 4 Entries enter the coal seam in this area. No other portals or highwalls exist. See attached map. The attached map is from Plate 5-3 Surface Facilities in the approved MRP. The location of the mine is in Section 5, T15S, R7E, SLBM.

2. Provide verification of highwall and adjacent cutslope creation dates. (At a minimum determine whether it was created before or after May 3, 1978.)

The mine was begun in the early 1970's. Production over the years was erratic. The mine was shut down. In 1983 the mine was reopened, using the existing portals & entries.

3. Provide a reference to the Mining and Reclamation Plan (MRP) which discusses the final reclamation and elimination or retention of the identified highwalls. If no reference exists, state "none".

No reference to elimination of highwalls exist in the approved MRP. Plans exist in the Crandall Creek Culvert Amendment to fully eliminate this area however.

Please return to Daron Haddock by March 7, 1997

